







<p><b>BETA ,BETA HPE</b> <b>1.4,1.6,1.8</b></p>  <p>10/1972-10/1974</p>	<p>N/A</p>	<p><b>250152</b> <b>LA2P</b> 82347928</p>	<p><b>230316</b> <b>LA110V</b> 82347941</p>
<p><b>BETA,BETA HPE</b> <b>1.3,1.6,2.0</b></p>  <p>→ch.no.22324 11/1974-11/1979</p>	<p><b>140102</b> <b>LA35C</b> 82320954</p>	<p><b>250152</b> <b>LA2P</b> 82347928</p>	<p><b>230316</b> <b>LA110V</b> 82347941</p>
<p><b>BETA HPE 1.6,2.0</b> <b>TREVI 1.6,2.0</b></p> <p>1585cc (74 kW,100 CV,HP,PS) 1995cc (90 kW,122 CV,HP,PS)</p>  <p>ch.no.22325→ 12/1979-1986</p>	<p><b>140102</b> <b>LA35C</b> 82371470</p>	<p><b>240149</b> <b>LA34D</b> 82376917</p>	<p><b>240148</b> <b>LA24T</b> 82384215</p>
<p><b>BETA COUPE,SPIDER</b> <b>1.4,1.6,1.8</b></p>  <p>→09/1974</p>	<p>N/A</p>	<p><b>230190</b> <b>LA6J</b> 82350434</p>	<p><b>220301</b> <b>LA112Q</b> 82350437</p>
<p><b>BETA COUPE,SPIDER</b> <b>1.3,1.6,1.8</b></p>  <p>10/1974-05/1980</p>	<p><b>140102</b> <b>LA35C</b> 82320954</p>	<p><b>230190</b> <b>LA6J</b> 82350434</p>	<p><b>220301</b> <b>LA112Q</b> 82350437</p>



510036



430192



430192



420093



510037



410128




430192



430192



420093



510007



410128




430192



430139



420093



510039



430192




430192



430010x2



420093



510040



410128



430192



430192



430010x2



420093

**140102**  
**LA35C**  
82320954


**230191**  
**LA22W**  
82376919

**230192**  
**LA23V**  
82369088

**BETA COUPE, SPIDER**  
**1.3, 1.6, 2.0, 2.0ie**



**06/1980-1986**



410128



430192



430139



430010x2



420093

510041